



Industrial 50 Spare Parts List



Top Corner Bracket



Cross Bar Joining Bracket




Corner Pull Pin Bracket



Collar and Pin



Sliding Mast Bracket



Lower Foot Plate

Industrial 50 Spare Parts List



Top Bracket from Middle Leg
on a 3M x 6m



Sliding Middle Leg Bracket from
a 3M x 6m



Top Leg Bracket from 6M Hex Model



Sliding Leg Bracket form 6M Xeh Model



50mm Nylock Nut and Bolt



35mm Nylock Nut and Bolt



Industrial 50 Spare Parts List



10 Grub Screws



Upper & Lower Mast Poles



Cross Bar Saddle and Bolt



Cross Bar Pair



Connector Bracket



Pull Pin



Lower Leg



Upper Leg