



Professional 40 Spare Parts List



Top Corner Bracket



Cross Bar Joining Bracket



Corner Pull Pin Bracket



Collar and Pin



Top Bracket from Middle Leg on
3M x 6M



Sliding Middle Leg Bracket from a
3M x 6M



Professional 40 Spare Parts List



Upper Mast Pole Lower Mast Pole



Mast Sliding Joint



Pull Pin



Cross Bar Pair



Lower Leg



Upper Leg